10/681534

C/C

OIPE JAN 18 2006 PATENT & TRADEMARK OFFICE IAP85

Practitioner's Docket No. SGL 02/25

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.	: US 6,979,377 B2	Confirmation No.: 7490
Patentee	: Rainer Bünis, et al.	
Issued	: Dec. 27, 2005	
Art Unit	: 1734	
Examiner	: Melvin C. Mayes	
Title	: Method for Producing Components from Fiber-Reinforced Composite Ceramic and Methods for Using the Components	
Docket No.	: SGL 02/25	
Customer No.	: 24131	

Certificate
JAN 24 2006
of Correction

Commissioner for Patents
P.O. Box 1450,
Alexandria, VA 22313-1450
ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.

2. The Document where the errors are shown correctly in the application file are:

   The reference numerals 1, 1', 2, 2' and 4, 4' appear correctly on pages 8- 12 of the specification in the original application filed in the U.S. Patent and Trademark Office on October 8, 2003.

3. Please send the Certificate to:

   Name : LERNER GREENBERG STEMER LLP
   Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

☐ Assignment recorded on

_____

Reel :_____
Frame:_____

_____
(name of authorized person signing

WERNER H. STEMER
REG. NO. 34,956

Attorney of Record
Title of authorized person signing

☐ Attached is a Recordal of assignment

☐ Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)"
(establishing the right of the assignee to take action in this case)

Date: _____

JAN 24 2006

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 3, line 45 should read as follows:

tools **2, 2'** (FIG. **1**) or by pleating, where by the tapes may

Column 3, line 46 should read as follows:

already contain a hardenable binder. The tapes **1, 1'** corre-

Column 3, line 49 should read as follows:

As represented in FIG. **2**, these tapes **1, 1'** are juxtaposed

Column 3, line 52 should read as follows:

adjoining tapes **1, 1'** touch only partly, namely int the contact

Column 3, line 53 should read as follows:

zones **4, 4'**, and are agglutinated by using a carbonizable

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

JAN 24 2006

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 3, line 54 should read as follows:

binder in the region of these contact zones **4, 4'**. Outside the

Column 3, line 55 should read as follows:

contact zones **4, 4'**, the tapes **1, 1'** are held the desired distance

Column 3, line 67 should read as follows:

surrounded by the tapes **1, 1'** are filled by the spacers **3**, so

Column 4, line 4 should read as follows:

the tapes **1, 1'** are joined into the prebody **10** at their contact

Column 4, line 5 should read as follows:

points **4, 4'**. As represented by the working line W in FIG. **3**,

Column 4, line 7 should read as follows:

continuously induced into all regions of the tapes **1, 1'** that

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

JAN 24 2006

PATENT NO. 6,979,377

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

JAN 24 2006

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 8 should read as follows:

include contact surfaces **4, 4'**; i.e., the mold pressure is

Column 4, line 10 should read as follows:

over a series of spacers **3** with the contact zones **4, 4'** of the

Column 4, line 11 should read as follows:

tapes **1, 1'** between them. The spacers **3** need not precisely fit

Column 4, line 13 should read as follows:

contact zones **4, 4'** that are joined by intensive pressure are

Column 4, line 17 should read as follows:

component **6** that the tapes **1, 1'** surrounded can be honeycomb

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

JAN 24 2006

PATENT NO. 6,979,377

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

JAN 24 2006

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 21 should read as follows:

openings **7** that are surrounded by the tapes **1, 1'**. It is enough

Column 4, line 22 should read as follows:

to construct the spacers such that they hold the tapes **1, 1'** the

Column 4, line 54 should read as follows:

contact zones **4, 4'**. A separate coat of glue is thus unneces-

Column 4, line 59 should read as follows:

enable, and they acquire their final shape as tapes **1, 1'** for the

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

JAN 24 2006

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 3, line 45 should read as follows:

tools **2, 2'** (FIG. **1**) or by pleating, where by the tapes may

Column 3, line 46 should read as follows:

already contain a hardenable binder. The tapes **1, 1'** corre-

Column 3, line 49 should read as follows:

As represented in FIG. **2,** these tapes **1, 1'** are juxtaposed

Column 3, line 52 should read as follows:

adjoining tapes **1, 1'** touch only partly, namely int the contact

Column 3, line 53 should read as follows:

zones **4, 4'**, and are agglutinated by using a carbonizable

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

JAN 24 2006

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 3, line 54 should read as follows:

binder in the region of these contact zones **4, 4'**. Outside the

Column 3, line 55 should read as follows:

contact zones **4, 4'**, the tapes **1, 1'** are held the desired distance

Column 3, line 67 should read as follows:

surrounded by the tapes **1, 1'** are filled by the spacers **3**, so

Column 4, line 4 should read as follows:

the tapes **1, 1'** are joined into the prebody **10** at their contact

Column 4, line 5 should read as follows:

points **4, 4'**. As represented by the working line W in FIG. **3**,

Column 4, line 7 should read as follows:

continuously induced into all regions of the tapes **1, 1'** that

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

JAN 24 2006

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 8 should read as follows:

include contact surfaces **4, 4'**; i.e., the mold pressure is

Column 4, line 10 should read as follows:

over a series of spacers **3** with the contact zones **4, 4'** of the

Column 4, line 11 should read as follows:

tapes **1, 1'** between them. The spacers **3** need not precisely fit

Column 4, line 13 should read as follows:

contact zones **4, 4'** that are joined by intensive pressure are

Column 4, line 17 should read as follows:

component **6** that the tapes **1, 1'** surrounded can be honeycomb

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

JAN 24 2006

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.

PTO/SB/44 (10-96)
Approved for use through 06/30/99. OMB 0651-0033
Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to repsond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO	:	US 6,979,377 B2
ISSUED	:	December 27, 2005
INVENTOR(S)	:	Rainer Bünis, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 21 should read as follows:

openings **7** that are surrounded by the tapes **1, 1'**. It is enough

Column 4, line 22 should read as follows:

to construct the spacers such that they hold the tapes **1, 1'** the

Column 4, line 54 should read as follows:

contact zones **4, 4'**. A separate coat of glue is thus unneces-

Column 4, line 59 should read as follows:

enable, and they acquire their final shape as tapes **1, 1'** for the

MAILING ADDRESS OF SENDER:

Lerner Greenberg Stemer
LLP
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,979,377

No. of additional copies

JAN 24 2006

JAN 24 2006

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Boc 1450, Alexandria, VA 22313-1450.